



**Brew MP Test Validation Report**  
QSC6085

Date: March 28, 2011



**QUALCOMM® Proprietary**

**Restricted Distribution:** This document contains critical information about QUALCOMM products and may not be distributed to anyone that is not an employee of QUALCOMM, its affiliates or subsidiaries without the approval of Configuration Management.

QUALCOMM Incorporated reserves the right to make changes to the product(s) or information contained herein without notice. No liability is assumed for any damages arising directly or indirectly by their use or application. The information provided in this document is provided on an "as is" basis.

All data and information contained in or disclosed by this document is confidential and proprietary information of QUALCOMM Incorporated and all rights therein are expressly reserved. By accepting this material the recipient agrees that this material and the information contained therein is to be held in confidence and in trust and will not be used, copied, reproduced in whole or in part, nor its contents revealed in any manner to others without the express written permission of QUALCOMM Incorporated.

QUALCOMM is a registered trademark and registered service mark of QUALCOMM Incorporated. Other product and brand names may be trademarks or registered trademarks of their respective owners.

Export of this technology may be controlled by the United States Government. Diversion contrary to U.S. law prohibited.

QUALCOMM Incorporated  
5775 Morehouse Drive  
San Diego, CA 92121-1714  
U.S.A.

Copyright © 2010 QUALCOMM Incorporated. All rights reserved.

# Table of Contents

<b>Section 1 Summary .....</b>	<b>4</b>
<b>Section 2 Brew MP Validation Results.....</b>	<b>5</b>
2.1 Brew MP QSC6085 Results Summary .....	5
2.1.1 Validation Environment Summary .....	5
2.1.2 Brew MP Validation Test Summary .....	5
2.1.3 Validation Issues Severity Summary .....	5
2.2 Brew MP Validation Issues Breakdown by Family .....	6
2.2.1 Connectivity .....	6
2.2.2 Databases .....	7
2.2.3 Deprecated .....	8
2.2.4 Hardware .....	8
2.2.5 Languages .....	9
2.2.6 Media .....	10
2.2.7 Networking .....	11
2.2.8 Performance .....	11
2.2.9 Security .....	12
2.2.10 System .....	12
2.2.11 Telephony .....	13
2.2.12 UI.....	15

## Section 1 Summary

The following report is intended to communicate how well Brew MP software, SDK & Tools, and platform perform on the QSC6085 when run against the PVS tests. The data contained herein is not intended to demonstrate any capability of the hardware itself.

Throughout the document there are many abbreviated and technical terms. If any of these terms are unfamiliar, please refer to the Brew MP Glossary on the [Brew MP website](#).

## Section 2 Brew MP Validation Results

### 2.1 Brew MP QSC6085 Results Summary

#### 2.1.1 Validation Environment Summary

Environment Attribute	Attribute Data
PVS Version	1.0.2.594 PRO
Test Studio Version	5.11.1.133
Brew MP Version	1.0.2.594
Device Build Version	Q6085CSNAAT533404

#### 2.1.2 Brew MP Validation Test Summary

Results Categories	Results Summary Data
Test Module Count	187
Test Modules Executed	13
Total Tests Passed	8923
Total Tests Failed	127
Total Features Unsupported	1956
Total Tests Unexecuted	856
Date of Execution	Sat Mar 12 2011

#### 2.1.3 Validation Issues Severity Summary

Issue Severity	High	Medium	Low	Unknown	Total
Totals	3	27	10	5	45

## 2.2 Brew MP Validation Issues Breakdown by Family

### 2.2.1 Connectivity

#### 2.2.1.1 Failures

Feature	Tests	Issue	Impact	Severity
OATBTClient	<ul style="list-style-type: none"> <li>OATBTClient_BIP-GetAttachment</li> <li>OATBTClient_BIP-GetCapabilities</li> <li>OATBTClient_BIP-GetImage</li> <li>OATBTClient_BIP-GetImageList</li> <li>OATBTClient_BIP-GetImageProperties</li> <li>OATBTClient_BIP-GetThumbnail</li> </ul>	Platform issue. Feature unverified	Applications may not be able to use Bluetooth interfaces.	Medium
	<ul style="list-style-type: none"> <li>OATBTClient_Secu-BondWithOOB</li> <li>OATBTClient_Secu-PinKeyReply</li> <li>OATBTClient_Secu-SetBondable</li> <li>OATBTClient_Secu-TestPasskeyRequest</li> </ul>	Platform issue. Feature unverified	Applications may not be able to use Bluetooth interfaces.	Medium
	<ul style="list-style-type: none"> <li>OATBTClient_DuN-Disable</li> <li>OATBTClient_DuN-Enable</li> </ul>	Platform issue. Feature unverified	Applications may not be able to use Bluetooth interfaces.	Medium
	<ul style="list-style-type: none"> <li>OATBTClient_EIR-localShortName</li> </ul>	Platform issue. Feature unverified	Applications may not be able to use Bluetooth interfaces.	Medium
	<ul style="list-style-type: none"> <li>OATBTClient_FTP-ChDir</li> <li>OATBTClient_FTP-Get</li> <li>OATBTClient_FTP-GetDir</li> <li>OATBTClient_FTP-LsDir</li> <li>OATBTClient_FTP-MkDir</li> <li>OATBTClient_FTP-Put</li> <li>OATBTClient_FTP-PutDir</li> <li>OATBTClient_FTP-Rmdir</li> </ul>	Platform issue. Feature unverified	Applications may not be able to use Bluetooth interfaces.	Medium
	<ul style="list-style-type: none"> <li>OATBTClient_Mgr-SetDiscoverableMode</li> <li>OATBTClient_Mgr-SetPrefConnRole</li> <li>OATBTClient_Mgr-SetRoleSwitchPolicy</li> </ul>	Platform issue. Feature unverified	Applications may not be able to use Bluetooth interfaces.	Medium
	<ul style="list-style-type: none"> <li>OATBTClient_OBEX-Connect</li> <li>OATBTClient_OBEX-Disconnect</li> <li>OATBTClient_OBEX-Get</li> <li>OATBTClient_OBEX-Put</li> <li>OATBTClient_OBEX-SendCommand</li> <li>OATBTClient_OBEX-SetPath</li> </ul>	Platform issue. Feature unverified	Applications may not be able to use Bluetooth interfaces.	Medium
	<ul style="list-style-type: none"> <li>OATBTClient_OPP-AbortPush</li> <li>OATBTClient_OPP-PullOwnerVCard</li> <li>OATBTClient_OPP-PushBytes</li> <li>OATBTClient_OPP-PushFile</li> <li>OATBTClient_OPP-PushLargeObject</li> <li>OATBTClient_OPP-RepullObject</li> </ul>	Platform issue. Feature unverified	Applications may not be able to use Bluetooth interfaces.	Medium
	<ul style="list-style-type: none"> <li>OATBTClient_PBAB-Connect</li> <li>OATBTClient_PBAB-Disconnect</li> <li>OATBTClient_PBAB-GetFilteredVCardListing</li> <li>OATBTClient_PBAB-PullPhoneBook</li> <li>OATBTClient_PBAB-PullPhoneBookSize</li> <li>OATBTClient_PBAB-PullVCardEntry</li> </ul>	Platform issue. Feature unverified	Applications may not be able to use Bluetooth interfaces.	Medium
	<ul style="list-style-type: none"> <li>OATBTClient_SPP-DisconnectFromSecServer</li> <li>OATBTClient_SPP-InitiateSecSPPCon</li> <li>OATBTClient_SPP-ReadDataSec</li> <li>OATBTClient_SPP-SendDataSec</li> </ul>	Platform issue. Feature unverified	Applications may not be able to use Bluetooth interfaces.	Medium

OATIBTServer	<ul style="list-style-type: none"> <li>OATBTCClient_FTC-Disable</li> </ul>	Platform issue. Feature unverified	Applications may not be able to use Bluetooth interfaces.	Medium
	<ul style="list-style-type: none"> <li>OATBTCClient_OPP-DisableService</li> <li>OATBTCClient_OPP-EnableService</li> <li>OATBTCClient_OPP-EnableServiceAndDisable</li> </ul>	Platform issue. Feature unverified	Applications may not be able to use Bluetooth interfaces.	Medium

Issue Severity	High	Medium	Low	Unknown	Total
Totals	0	12	0	0	12

### 2.2.1.2 Unexecuted

Test Module	Tests	Reason	Impact
Conmgrtest (14)	<ul style="list-style-type: none"> <li>All</li> </ul>	Incorrect test framework configuration. .Feature unsupported.	None
Ctfwlanprofilemgr (64)	<ul style="list-style-type: none"> <li>All</li> </ul>	Incorrect test framework configuration. .Feature unsupported.	None
Ctfwlansettings (14)	<ul style="list-style-type: none"> <li>All</li> </ul>	Incorrect test framework configuration. Feature unsupported.	None

## 2.2.2 Databases

### 2.2.2.1 Failures

Feature	Tests	Issue	Impact	Severity
None				

Issue Severity	High	Medium	Low	Unknown	Total
Totals	0	0	0	0	0

### 2.2.2.2 Unexecuted

Feature	Tests	Reason	Impact
Contacts Management (190)	<ul style="list-style-type: none"> <li>ctfcontactstest</li> </ul>	Incorrect test framework configuration. Test issue. Feature manually verified.	None
	<ul style="list-style-type: none"> <li>ctfdbctest</li> </ul>	Incorrect test framework configuration. Test issue. Feature manually verified.	None
	<ul style="list-style-type: none"> <li>ctfcontactssperftest – All</li> </ul>	Incorrect test framework configuration. Test issue. Feature manually verified.	None
	<ul style="list-style-type: none"> <li>ctfcontactstoretest - All</li> </ul>	Incorrect test framework configuration. Test issue. Feature manually verified.	None
SIM Card (49)	<ul style="list-style-type: none"> <li>ctfadntest - All</li> </ul>	Incorrect test framework configuration. Test issue. Feature manually verified.	None

Gallery (2)	<ul style="list-style-type: none"> <li>MountDuringSync</li> <li>UnmountDuringSync</li> </ul>	Incorrect test framework configuration. Test obsolete.	None
-------------	--	--	------

## 2.2.3 Deprecated

### 2.2.3.1 Failures

Feature	Tests	Issue	Impact	Severity
Telephone Layer Interface	<ul style="list-style-type: none"> <li>TAPI_SendSMS_ToThisHandset</li> </ul>	Under investigation. Feature unverified.	Unknown	Unknown
Text Input Controller	<ul style="list-style-type: none"> <li>Text_InputModes</li> <li>Text_TextInputs</li> <li>Text_TextSetPropertiesMultiline</li> </ul>	Platform issue. Feature unverified.	Extended keys feature is incorrect in device build. Multitap does not work.	High
USB Driver	<ul style="list-style-type: none"> <li>USBDriver_ReceiveBulkOut_PerfEFTFile</li> </ul>	Incorrect test framework configuration. Test issue. Feature unverified.	Data transfers may be slow.	Low

Issue Severity	High	Medium	Low	Unknown	Total
Totals	1	0	1	1	3

### 2.2.3.2 Unexecuted

Test Module	Tests	Reason	Impact
None			

## 2.2.4 Hardware

### 2.2.4.1 Failures

Feature	Tests	Issue	Impact	Severity
Camera	<ul style="list-style-type: none"> <li>Camera1_FSMonitorSnapshot</li> <li>Camera1_FSMonitorMovie</li> </ul>	Incorrect test framework configuration. Feature unverified.	Files may be overwritten.	Medium
OEM-Configurable Variables and Interfaces	<ul style="list-style-type: none"> <li>Device_AlertBeep</li> <li>Device_ErrorBeep</li> <li>Device_MsgBeep</li> <li>Device_RemindBeep</li> </ul>	IShell_Beep is not playing any system beeps.	Applications will not be able to play desired tones.	Medium
	<ul style="list-style-type: none"> <li>Device_Device_NativeCamera</li> </ul>	Incorrect test framework configuration. Test issue. Feature unverified.	Applications may not have access to pictures taken with the native camera application	Low
Touchscreen Pointer Events	<ul style="list-style-type: none"> <li>Pointer_MultiTouch</li> </ul>	Incorrect test framework configuration. Test issue.	None	Low



		Feature unsupported on FFA.		
<b>Position Determination</b>	<ul style="list-style-type: none"> <li>PosDet_SetConfig.1</li> </ul>	Incorrect test framework configuration. Test obsolete.	None	Low
<b>USB Driver Interface</b>	<ul style="list-style-type: none"> <li>USBDevice_ReceiveBulkOut_PerEFTFile</li> </ul>	Incorrect framework configuration. Test issue. Feature unverified.	Data transfers may be slow.	Low

Issue Severity	High	Medium	Low	Unknown	Total
<b>Totals</b>	0	2	4	0	6

### 2.2.4.2 Unexecuted

Test Module	Tests	Reason	Impact
None			

## 2.2.5 Languages

### 2.2.5.1 Failures

Feature	Test	Issue	Impact	Severity
None				

Issue Severity	High	Medium	Low		Total
<b>Totals</b>	0	0	0	0	0

### 2.2.5.2 Unexecuted

Test Module	Test	Reason	Impact
Ctfluatest (43)	<ul style="list-style-type: none"> <li>All</li> </ul>	Incorrect test framework configuration. Test issue. Feature manually verified.	Lua applications may not execute.
OATJams_lapp (82)	<ul style="list-style-type: none"> <li>All</li> </ul>	Incorrect test framework configuration. Test issue. Feature unsupported.	None
OATJams_lappControl (89)	<ul style="list-style-type: none"> <li>All</li> </ul>	Incorrect test framework configuration. Test issue. Feature unsupported.	None
OATJams_lappJSR229 (15)	<ul style="list-style-type: none"> <li>All</li> </ul>	Incorrect test framework configuration. Test issue. Feature unsupported.	None
OATJams_lappSession (49)	<ul style="list-style-type: none"> <li>All</li> </ul>	Incorrect test framework configuration. Test issue. Feature unsupported.	None
OATJams_lappSessionJ SR82 (5)	<ul style="list-style-type: none"> <li>All</li> </ul>	Incorrect test framework configuration. Test issue. Feature	None

		unsupported.	
OATJams_AutoInstall (1)	<ul style="list-style-type: none"> <li>All</li> </ul>	Incorrect test framework configuration. Test issue. Feature unsupported.	None
OATJams_Install (82)	<ul style="list-style-type: none"> <li>All</li> </ul>	Incorrect test framework configuration. Test issue. Feature unsupported.	None
OATJams_Sanity (6)	<ul style="list-style-type: none"> <li>All</li> </ul>	Incorrect test framework configuration. Test issue. Feature unsupported.	None
OATJams_Smoke (3)	<ul style="list-style-type: none"> <li>All</li> </ul>	Incorrect test framework configuration. Test issue. Feature unsupported.	None

## 2.2.6 Media

### 2.2.6.1 Failures

Feature	Tests	Issue	Impact	Severity
Media Content Preview	<ul style="list-style-type: none"> <li>ContentPreview_Mp3MultiBufferPreview</li> </ul>	Platform issue. Crash. Feature unverified.	Applications or services using album art for mp3 files may not function properly.	High
Multimedia	<ul style="list-style-type: none"> <li>Media_PlayAudioCapsOnAudioVideoClip</li> <li>Media_PlayVideoCapsOnAudioVideoClip</li> <li>MediaVideo_PlayAudioCapsOnAudioVideoClip</li> <li>MediaVideo_PlayVideoCapsOnAudioVideoClip</li> </ul>	Device is unable to play only audio or video for a 3gp clip.	Applications will not be able to play 3gp audio or video files	Medium
MediaFileSystem Monitor	<ul style="list-style-type: none"> <li>Media_FSMonitorRecordMedia.1</li> </ul>	FSMonitor not supported on device. Feature unverified.	Application cannot monitor file creation using Imedia_Record. Files may be overwritten.	Medium
ExternalMediaDevices	<ul style="list-style-type: none"> <li>MediaDevice_HeadsetActive</li> <li>MediaDevice_HeadsetBackgroundInsert</li> <li>MediaDevice_HeadsetBackgroundRemove</li> <li>MediaDevice_HeadsetEvent</li> <li>MediaDevice_HeadsetUnloaded</li> </ul>	Incorrect test framework configuration. Test issue. Feature unverified.	Headset insertion/removal events are not recognized by device.	Medium
Ringer	<ul style="list-style-type: none"> <li>Ringer_Remove</li> <li>Ringer_VerifyRingers</li> </ul>	Incorrect test framework configuration. Test issue. Feature manually verified.	None	Low

Issue Severity	High	Medium	Low		Total
Totals	1	3	1	0	5

### 2.2.6.2 Unexecuted

Test Module	Tests	Reason	Impact
MediaDevice (1)	<ul style="list-style-type: none"> <li>MediaDevice_StereoAudioFiles</li> </ul>	Incorrect test framework configuration.	Audio output to supported devices may

		Test issue. Feature unverified	not work correctly.
<b>MediaAMR (36)</b>	<ul style="list-style-type: none"> <li>All except MimeSupport</li> </ul>	Incorrect test framework configuration. Test issue. Feature unsupported.	None
<b>MediaEVW (36)</b>	<ul style="list-style-type: none"> <li>All except MimeSupport</li> </ul>	Incorrect test framework configuration. Test issue. Feature unsupported.	None
<b>OMADRM (1)</b>	<ul style="list-style-type: none"> <li>DrawDCF</li> </ul>	Incorrect test framework configuration. Test issue. Feature unsupported.	None

## 2.2.7 Networking

### 2.2.7.1 Failures

Feature	Tests	Issue	Impact	Severity
<b>DNS</b>	<ul style="list-style-type: none"> <li>DNS_GetResponse.1</li> </ul>	Under investigation. Feature unverified.	Unknown	Unknown
<b>Network</b>	<ul style="list-style-type: none"> <li>Network_Ipv4_SelectNetworkEx.12, .14</li> </ul>	DPK issue. Feature unverified.	Applications will not be able to explicitly select UICC or FMC networks.	Low
<b>Socket Routines</b>	<ul style="list-style-type: none"> <li>Socket_Accept.3</li> <li>Socket_Close.3</li> <li>Shutdown.5</li> </ul>	Incorrect test framework configuration. Test issue. Feature unverified.	Network server applications may have failures managing TCP connections	Medium
	<ul style="list-style-type: none"> <li>Socket_Stress.3</li> </ul>	Incorrect test framework configuration. Test issue. Feature unverified.	Network applications may fail during period of high network activity.	Low
<b>Socket Port Number Routines</b>	<ul style="list-style-type: none"> <li>SockPort_Accept.3</li> <li>SockPort_Close.3</li> <li>SockPort_IPv4_Accept.3</li> <li>SockPort_IPv4_Close.3</li> <li></li> </ul>	Incorrect test framework configuration. Test issue. Feature unverified.	Network server applications may have failures managing TCP connections	Medium

Issue Severity	High	Medium	Low	Unknown	Total
<b>Totals</b>	0	2	2	1	5

### 2.2.7.2 Unexecuted

Test Module	Test	Reason	Impact
<b>Proxy (11)</b>	All	Under investigation. Feature unverified.	Unknown

## 2.2.8 Performance

### 2.2.8.1 Failures

Feature	Tests	Issue	Impact	Severity
<b>PerfShell</b>	<ul style="list-style-type: none"> <li>PerfShell_Ishell_CreateInstance_ISSL_Test</li> </ul>	Under investigation. Feature unverified.	Unknown	Unknown

Issue Severity	High	Medium	Low	Unknown	Total
Totals	0	0	0	1	1

### 2.2.8.2 Unexecuted

Test Module	Test	Reason	Impact
None			

## 2.2.9 Security

### 2.2.9.1 Failures

Feature	Tests	Issue	Impact	Severity
CTFTestRootExistence	<ul style="list-style-type: none"> <li>CTFTestRootExistence_TestRootExistenceTest</li> </ul>	Expected to fail with internal CRM device build. Must pass on commercial device build.	None	Low

Issue Severity	High	Medium	Low	Unknown	Total
Totals	0	0	1	0	1

### 2.2.9.2 Unexecuted

Test Module	Test	Reason	Impact
None			

## 2.2.10 System

### 2.2.10.1 Failures

Feature	Tests	Issue	Impact	Severity
ACM	<ul style="list-style-type: none"> <li>ACM_MidiWaitsOnPMD</li> </ul>	Investigating. Feature unverified	Unknown	Unknown
Background-running applications	<ul style="list-style-type: none"> <li>Background_BGAudioFGVoice</li> </ul>	Incorrect test framework configuration. Test issue. Feature is unverified.	An incoming voice when a background app is playing audio may not have audio resources available for it to play functional audio.	Medium
	<ul style="list-style-type: none"> <li>Background_EndKeyBGVoice</li> </ul>	Incorrect test framework configuration. Test issue. Feature is unverified.	Voice called may be interrupted.	Medium
	<ul style="list-style-type: none"> <li>Background_LaunchDuringVoice</li> </ul>	Incorrect test framework configuration. Test issue	None	Low

		Feature unsupported.		
	<ul style="list-style-type: none"> <li>Background_Background_PowerDown</li> </ul>	Incorrect test framework configuration. Test issue. Feature unverified.	Background applications are not notified of power down	Medium
<b>MemMapTest</b>	<ul style="list-style-type: none"> <li>MemMapTest_GetInfoTest</li> <li>MemMapTest_ResizeTest</li> </ul>	Incorrect test framework configuration. Test issue. Feature unverified.	Applications may not be able to use the IMemMap interface.	Medium
<b>MemRegionTest</b>	<ul style="list-style-type: none"> <li>MemRegionTest_GetInfoTest2</li> </ul>	Incorrect test framework configuration. Test issue. Feature unverified.	Data written to reserved area may end up using the unreserved area of the file system.	Medium

Issue Severity	High	Medium	Low	Unknown	Total
<b>Totals</b>	0	5	1	1	7

## 2.2.10.2 Unexecuted

Test Module	Test	Reason	Impact
<b>FSMonitorTest (32)</b>	All	Incorrect test framework configuration. Test issue. Feature unverified.	Applications may not be able to use the IFSMonitor, IFSMonitorEntity interfaces.
<b>MemShareTest (13)</b>	All	Incorrect test framework configuration. Test issue. Feature unverified.	Applications may not be able to use the IMemShare interface.
<b>OutOfCoverage (1)</b>	Coverage	Incorrect test framework configuration. Test issue. Feature unverified.	Device may be unable to determine and report coverage status.
<b>PrivSetTest (10)</b>	All	Incorrect test framework configuration. Test issue. Feature unverified.	Applications may not be able to use the IPrivSet interface.
<b>SysClockTest (5)</b>	SysClockTest_CheckValidityStateShar ed SysClockTest_Interdependence SysClockTest_MultiInstanceOnChang e SysClockTest_OnChange SysClockTest_SetTimeUS	Incorrect test framework configuration. Test issue. Feature unverified.	Applications may not be able to use the lsysClock interface.
<b>Thread (9)</b>	Thread_ThreadExit Thread_ThreadGetResumeCBK Thread_ThreadHoldRsc Thread_Threadjoin Thread_ThreadMalloc Thread_ThreadMisalignCheck Thread_ThreadStart Thread_ThreadStop Thread_ThreadSuspend	Incorrect test framework configuration. Test issue. Feature unverified.	Unknown

## 2.2.11 TAPI

### 2.2.11.1 Failures

Feature	Tests	Issue	Impact	Severity
None	•			

Issue Severity	High	Medium	Low	Unknown	Total
Totals	0	0	1	0	1

### 2.2.11.2 Unexecuted

Test Module	Test	Reason	Impact
None			

## 2.2.12 Telephony

### 2.2.12.1 Failures

Feature	Tests	Issue	Impact	Severity
SMS	<ul style="list-style-type: none"> <li>SMS_SRPRIVCONF_Default</li> <li>SMS_SRPRIVRES_Default</li> <li>SMS_SRPRIVSEC_Default</li> </ul>	Incorrect test framework configuration. Test issue. Feature unverified.	Failure to send SMS with specified privilege.	High
	<ul style="list-style-type: none"> <li>SMS_SRUDHNATLANGLS_NoPayload</li> <li>SMS_SRUDHNATLANGSS_NoPayload</li> <li>SMS_STRDNVUDHNATLANGLS_NoPayload</li> <li>SMS_STRDNVUDHNATLANGLSS_NoPayload</li> <li></li> </ul>	Platform issue. Feature unverified.	National Language Feature will not work.	Medium
	<ul style="list-style-type: none"> <li>SMS_SRUDHPORT16_NoPayload</li> <li>SMS_SRUDHPORT16_NoPayload</li> </ul>	Platform issue. Feature unverified.	Port-directed Notified will not work.	Medium
Services for managing the phone resources	<ul style="list-style-type: none"> <li>Telephone_BurstDTMF</li> <li>Telephone_StartDTMF</li> <li>Telephone_StopDTMF</li> </ul>	Under investigation. Feature unverified.	Unknown	Unknown
Telephone	<ul style="list-style-type: none"> <li>Telephone_OriginateCSData</li> </ul>	Incorrect test framework configuration. Test issue. Feature unverified.	Cannot originate CS data calls.	Medium

Issue Severity	High	Medium	Low	Unknown	Total
Totals	1	3	0	1	5

### 2.2.12.2 Unexecuted

Test Module	Tests	Reason	Impact
SMS (1)	<ul style="list-style-type: none"> <li>SMS_STRDUPDATESTATUSREPORT_Default</li> </ul>	Incorrect test framework configuration. Test issue. Obsolete test.	None

## 2.2.13 UI

### 2.2.13.1 Failures

Feature	Tests	Issue	Impact	Severity
None	•			

Issue Severity	High	Medium	Low	Unknown	Total
Totals	0	0	0	0	0

### 2.2.13.2 Unexecuted

Test Module	Test	Reason	Impact
WidgetTCt (1)	Multitouch	Incorrect test framework configuration. Test issue. Feature unsupported.	None