



**Brew MP API Validation Report**  
QSC6270 4.1 1.0.4.281.1

Date: May 11, 2011



**QUALCOMM® Proprietary**

**Restricted Distribution:** This document contains critical information about QUALCOMM products and may not be distributed to anyone that is not an employee of QUALCOMM, its affiliates or subsidiaries without the approval of Configuration Management.

QUALCOMM Incorporated reserves the right to make changes to the product(s) or information contained herein without notice. No liability is assumed for any damages arising directly or indirectly by their use or application. The information provided in this document is provided on an "as is" basis.

All data and information contained in or disclosed by this document is confidential and proprietary information of QUALCOMM Incorporated and all rights therein are expressly reserved. By accepting this material the recipient agrees that this material and the information contained therein is to be held in confidence and in trust and will not be used, copied, reproduced in whole or in part, nor its contents revealed in any manner to others without the express written permission of QUALCOMM Incorporated.

QUALCOMM is a registered trademark and registered service mark of QUALCOMM Incorporated. Other product and brand names may be trademarks or registered trademarks of their respective owners.

Export of this technology may be controlled by the United States Government. Diversion contrary to U.S. law prohibited.

QUALCOMM Incorporated  
5775 Morehouse Drive  
San Diego, CA 92121-1714  
U.S.A.

Copyright © 2010 QUALCOMM Incorporated. All rights reserved.

# Table of Contents

<b>Section 1 Summary .....</b>	<b>4</b>
<b>Section 2 Brew MP Validation Results.....</b>	<b>5</b>
2.1 Brew MP QSC6270 4.1 1.0.4.281.1 Results Summary .....	5
2.1.1 Validation Environment Summary .....	5
2.1.2 API Validation Results Summary.....	5
2.1.3 Validation Issues Severity Summary .....	5
2.2 API Validation Issues Breakdown by Family .....	6
2.2.1 Connectivity .....	6
2.2.2 Databases.....	8
2.2.3 Deprecated .....	8
2.2.4 Hardware .....	9
2.2.5 Languages .....	10
2.2.6 Media .....	11
2.2.7 Networking.....	12
2.2.8 Performance .....	12
2.2.9 Security .....	13
2.2.10 System .....	13
2.2.11 TAPI .....	14
2.2.12 Telephony .....	14
2.2.13 UI.....	15

## Section 1 Summary

The following report is intended to communicate how well Brew MP software, SDK & Tools, and platform perform on the QSC6270 4.1 when run against the PVS tests. The data contained herein is not intended to demonstrate any capability of the hardware itself.

Throughout the document there are many abbreviated and technical terms. If any of these terms are unfamiliar, please refer to the Brew MP Glossary on the [Brew MP website](#).

## Section 2 Brew MP Validation Results

### 2.1 Brew MP QSC6270 4.1 1.0.4.281.1 Results Summary

#### 2.1.1 Validation Environment Summary

Environment Attribute	Attribute Data
PVS Version	1.0.4.281.1 PRO
Test Studio Version	5.11.2.133
Brew MP Version	1.0.4.281.1
Device Build Version	Q6270BKPSQL421010

#### 2.1.2 API Validation Results Summary

Results Categories	Results Summary Data
Test Module Count	226
Test Modules Executed	221
Total Tests Passed	10225
Total Tests Failed	284
Total Features Unsupported	2024
Total Tests Unexecuted	764
Date of Execution	Mon May 2 2011

#### 2.1.3 Validation Issues Severity Summary

Issue Severity	High	Medium	Low	Unknown	Total
Totals	5	10	17	0	32

## 2.2 API Validation Issues Breakdown by Family

### 2.2.1 Connectivity

#### 2.2.1.1 Failures

Feature	Tests	Issue	Impact	Severity
<b>Connection Manager</b>	<ul style="list-style-type: none"> <li>Conmgrtest_Connect</li> <li>Conmgrtest_ScanAbort</li> <li>Conmgrtest_ScanMultipleListener</li> <li>Conmgrtest_ScanOnce</li> </ul>	Platform issue. Under investigation.	Cannot establish a WLAN connection.	High
<b>ctffmradioirx</b>	<ul style="list-style-type: none"> <li>ctffmradioirx_NoDeviceSupport</li> </ul>	Incorrect test framework configuration. Feature unsupported.	None	Low
<b>ctffmradioitx</b>	<ul style="list-style-type: none"> <li>ctffmradioitx_NoDeviceSupport</li> </ul>	Incorrect test framework configuration. Feature unsupported.	None	Low
<b>ctffmrds</b>	<ul style="list-style-type: none"> <li>ctffmrds_NoDeviceSupport</li> </ul>	Incorrect test framework configuration. Feature unsupported.	None	Low
<b>Bluetooth</b>	<ul style="list-style-type: none"> <li>OATIBTClient_BIP-GetAttachment</li> <li>OATIBTClient_BIP-GetCapabilities</li> <li>OATIBTClient_BIP-GetImage</li> <li>OATIBTClient_BIP-GetImageList</li> <li>OATIBTClient_BIP-GetImageProperties</li> <li>OATIBTClient_BIP-GetThumbnail</li> <li>OATIBTClient_FTP-ChDir</li> <li>OATIBTClient_FTP-Get</li> <li>OATIBTClient_FTP-GetMultiple-Files</li> <li>OATIBTClient_FTP-GetDir</li> <li>OATIBTClient_FTP-LsDir</li> <li>PATIBTClient_MkDir</li> <li>OATIBTClient_FTP-Put</li> <li>OATIBTClient_FTP-Put-MultipleFile</li> <li>OATIBTClient_FTP-PutDir</li> <li>OATIBTClient_FTP-Rmdir</li> <li>OATIBTClient_OBEX-Disconnect</li> <li>OATIBTClient_OBEX-Get</li> <li>OATIBTClient_OBEX-SendCommand</li> <li>OATIBTClient_OPP-GetServerSupportedFormats</li> <li>OATIBTClient_OPP-PullOwnerVCard</li> <li>OATIBTClient_OPP-PushBytes</li> <li>OATIBTClient_OPP-PushFile</li> <li>OATIBTClient_OPP-PushLargeObject</li> <li>OATIBTClient_OPP-RepullObject</li> <li>OATIBTClient_PBAP-AbortPullPhoneBook</li> <li>OATIBTClient_PBAP-Connect</li> <li>OATIBTClient_PBAP-Disconnect</li> <li>OATIBTClient_PBAP-GetFilteredVCardListing</li> <li>OATIBTClient_PBAP-PullPhoneBook</li> <li>OATIBTClient_PBAP-PullPhoneBookSize</li> <li>OATIBTClient_PBAP-PullVCardEntry</li> </ul>	OBEX authentication unsupported on QSC6270 and must be disabled.	Some Bluetooth profiles may not work properly.	High

WiFi	<ul style="list-style-type: none"> <li>WiFi_TransferWiFiData.1-5</li> </ul>	Platform issue. Under investigation.	Applications cannot transfer data using WiFi.	Medium
------	---	--------------------------------------	---	--------

Issue Severity	High	Medium	Low	Unknown	Total
Totals	2	1	3	0	6

### 2.2.1.2 Unexecuted

Test Module	Tests	Reason	Impact
ctffmradioirx (20)	<ul style="list-style-type: none"> <li>ctffmradioirx_AntennalsAvailable</li> <li>ctffmradioirx_ConfigureReceiver</li> <li>ctffmradioirx_DisableReceiver</li> <li>ctffmradioirx_EnableAudio</li> <li>ctffmradioirx_EnableReceiver</li> <li>ctffmradioirx_GetAudioSettings</li> <li>ctffmradioirx_GetParameter</li> <li>ctffmradioirx_GetParameterChanges</li> <li>ctffmradioirx_GetStationParams</li> <li>ctffmradioirx_GetStationParamsData</li> <li>ctffmradioirx_GetTuneFrequency</li> <li>ctffmradioirx_GetValidFreqRange</li> <li>ctffmradioirx_OnParamsChange</li> <li>ctffmradioirx_OnStationParamsChange</li> <li>ctffmradioirx_RDSSearchStations</li> <li>ctffmradioirx_RouteAudio</li> <li>ctffmradioirx_SearchStationList</li> <li>ctffmradioirx_SearchStations</li> <li>ctffmradioirx_StParams</li> <li>ctffmradioirx_SetStation</li> </ul>	Incorrect test framework configuration. Feature unsupported.	Low
ctffmradioitx (14)	<ul style="list-style-type: none"> <li>ctffmradioitx_AntennalsAvailable</li> <li>ctffmradioitx_Configure</li> <li>ctffmradioitx_CtrlRDSGrpTran</li> <li>ctffmradioitx_Disable</li> <li>ctffmradioitx_Enable</li> <li>ctffmradioitx_GetConfiguration</li> <li>ctffmradioitx_GetGPSFeatures</li> <li>ctffmradioitx_GetRDSGrpsBufSize</li> <li>ctffmradioitx_RouteAudio</li> <li>ctffmradioitx_SetStation</li> <li>ctffmradioitx_SetStationPSInfo</li> <li>ctffmradioitx_SetStationRTInfo</li> <li>ctffmradioitx_StoopRDSInfo</li> <li>ctffmradioitx_TransmitRDSGroups</li> </ul>	Incorrect test framework configuration. Feature unsupported.	Low
ctffmrds (18)	<ul style="list-style-type: none"> <li>ctffmrds_DisableFM</li> <li>ctffmrds_EnableFM</li> <li>ctffmrds_GetAF</li> <li>ctffmrds_GetAFInfo</li> <li>ctffmrds_GetPS</li> <li>ctffmrds_GetPSInfo</li> <li>ctffmrds_GetRawGroupData</li> <li>ctffmrds_GetRT</li> <li>ctffmrds_GetRTInfo</li> <li>ctffmrds_GetAFAvbl</li> <li>ctffmrds_OnProgramServiceAvbl</li> <li>ctffmrds_OnRadioTextAvbl</li> <li>ctffmrds_OnRawGroupDatavbl</li> <li>ctffmrds_RegRdsGroupProcessing.AF</li> <li>ctffmrds_RegRdsGroupProcessing.PS</li> </ul>	Incorrect test framework configuration. Feature unsupported.	Low

	<ul style="list-style-type: none"> <li>ctffmrds_RegRdsGroupProcessing.RT</li> <li>ctffmrds_SetRDSProcessingOptions</li> <li>ctffmrds_SetStation</li> </ul>		
--	--	--	--

## 2.2.2 Databases

### 2.2.2.1 Failures

Feature	Tests	Issue	Impact	Severity
<b>OMADS</b>	<ul style="list-style-type: none"> <li>CojntactsDataStoreHandlerTest_5_CapabilitiesTest</li> <li>DSCClientSyncSettingsTest_DSClientSincSettingsTestDSTest*</li> <li>DSCContactsSync01Test_DSContactsSync01TestDSTest*</li> <li>DSCContactsSync02Test_&lt;All&gt;</li> <li>DSCContactsSync03Test_&lt;All&gt;</li> <li>DSCContactsSync04Test_&lt;All&gt;</li> </ul>	Platform issue.	Settings cannot be synchronized using the ds_IDataStoreHandler and ds_IDSSession interfaces. Synchronization with the server will fail.	High
<b>Personal Information Manager</b>	<ul style="list-style-type: none"> <li>PIMCalendarStoreint_&lt;All Interactive&gt;</li> <li>PIMCallHistoryiInt_Addition</li> <li>PIMCallHistoryiInt_Deletion</li> <li>PIMCallHistoryiInt_DeletionFromUI</li> <li>PIUpdateMCallHistoryiInt_Update</li> <li>PIMUpdateFromUI</li> <li>PIMContactsint_&lt;All Interactive&gt;</li> <li>PIMMessageStoreInt_All interactive</li> </ul>	Platform issue.	JetUI has its own proprietary data store.	Low

Issue Severity	High	Medium	Low	Unknown	Total
<b>Totals</b>	1	0	1	0	2

### 2.2.2.2 Unexecuted

Feature	Tests	Reason	Impact
<b>SIM Card (1)</b>	<ul style="list-style-type: none"> <li>ctfadntest_VerifySupportforRemoveAllRecords</li> </ul>	Incorrect test framework configuration. Test issue. Feature unverified.	The deprecated API pim_IContacts_RemoveAllRecords may not be able to return EUNSUPPORTED.
<b>OMADS (4)</b>	<ul style="list-style-type: none"> <li>DSCClientSyncSettingsTest_DSClientSyncSettingsTest</li> <li>DSCContactSync01Test_DSContactSync01</li> <li>DSCContactSync03Test_DSContactSync03</li> <li>DSCContactSync04Test_DSContactSync04</li> </ul>	Platform Issue.	Settings cannot be synchronized using the ds_IDataStoreHandler and ds_IDSSession interfaces. Synchronization with the server will fail.

## 2.2.3 Deprecated

### 2.2.3.1 Failures

Feature	Tests	Issue	Impact	Severity
<b>AddrBook</b>	AddrBook_AddtoNative.2	Incorrect test framework	None	Low



	AddrBook_ReadFromNative.2	configuration. Test issue. Tests obsolete.		
--	---------------------------	---	--	--

Issue Severity	High	Medium	Low	Unknown	Total
Totals	0	0	1	0	1

### 2.2.3.2 Unexecuted

Test Module	Tests	Reason	Impact
TAPI1 (15)	All interactive	Incorrect test framework configuration. Test issue. Feature unverified.	Device may not be able to obtain phone number for incoming call in progress or outgoing call.

## 2.2.4 Hardware

### 2.2.4.1 Failures

Feature	Tests	Issue	Impact	Severity
Keypad	<ul style="list-style-type: none"> <li>ctfkeysconfigtest (all)</li> <li>ctfkeysmappingtest (all)</li> </ul>	Incorrect test framework configuration. Test issue. Feature unsupported.	None	Low
OEM-Configurable Variables and Interfaces	<ul style="list-style-type: none"> <li>Device_AlertBeep</li> <li>Device_ErrorBeep</li> <li>Device_MsgBeep</li> <li>Device_RemindBeep</li> </ul>	IShell_Beep is not playing any system beeps.	Applications will not be able to play desired tones.	Medium
	<ul style="list-style-type: none"> <li>Device_GetConfigComplex.1-2</li> </ul>	Incorrect test framework configuration. Test issue.	Test expects DNS information in NV; does not read it from SIM.	Low
	<ul style="list-style-type: none"> <li>Device_Keyguard</li> </ul>	Incorrect test framework configuration. Test issue. Feature unverified.	Leyguard events may not be recognized.	Low
	<ul style="list-style-type: none"> <li>Device_NativeNotifier</li> </ul>	Incorrect test framework configuration. Test issue. Feature unverified.	Native notified usupport is not enabled in Jet UI.	Low
HID	<ul style="list-style-type: none"> <li>SupportedRumbleTests</li> </ul>	Test execution error. Feature unverified.	It may not be possible to set Rumble correctly.	Low
Key	<ul style="list-style-type: none"> <li>KeyTones</li> </ul>	Platform issue.	Key tone volume can be set in the Jet UI but tones are not audible in BREW.	Medium
Position Determination	<ul style="list-style-type: none"> <li>PDTest_PDTest_FixCriteriaTwo_MSA</li> </ul>	Incorrect test framework configuration. Test issue.	Back-to-back fixes may not be processed correctly.	Low

	<ul style="list-style-type: none"> <li>PosDet_MPD_ModeLocalNetwork</li> <li>PosDet_SetConfig_Network_OptAccuracy</li> <li>PosDet_SetConfig_Network_OptSpeed</li> </ul>	Incorrect test framework configuration. Test issue.	Back-to-back fixes may not be processed correctly.	Low
--	--	---	--	-----

Issue Severity	High	Medium	Low	Unknown	Total
Totals	0	2	7	0	9

## 2.2.4.2 Unexecuted

Test Module	Tests	Reason	Impact
None			

## 2.2.5 Languages

### 2.2.5.1 Failures

Feature	Tests	Issue	Impact	Severity
None				

Issue Severity	High	Medium	Low	Unknown	Total
Totals	0	0	0	0	0

### 2.2.5.2 Unexecuted

Test Module	Tests	Reason	Impact
OATJams_lapp (82)	<ul style="list-style-type: none"> <li>All Unsupported except Report test.</li> </ul>	Incorrect test framework configuration. Feature manually verified.	None
OATJams_lappControl (89)	<ul style="list-style-type: none"> <li>All Unsupported except Report test.</li> </ul>	Incorrect test framework configuration. Feature unsupported.	None
OATJams_lappJSR229 (15)	<ul style="list-style-type: none"> <li>All Unsupported except Report test.</li> </ul>	Incorrect test framework configuration. Feature unsupported.	None
OATJams_lappSession (49)	<ul style="list-style-type: none"> <li>All Unsupported except Report test.</li> </ul>	Incorrect test framework configuration. Feature unsupported.	None
OATJams_lappSessionJ SR82 (5)	<ul style="list-style-type: none"> <li>All Unsupported except Report test.</li> </ul>	Incorrect test framework configuration. Feature unsupported.	None
OATJams_AutoInstall (1)	<ul style="list-style-type: none"> <li>All Unsupported except Report test.</li> </ul>	Incorrect test framework configuration. Feature unsupported.	None
OATJams_linstall (82)	<ul style="list-style-type: none"> <li>All Unsupported except Report test.</li> </ul>	Incorrect test framework configuration. Feature unsupported.	None

<b>OATJams_Sanity (6)</b>	<ul style="list-style-type: none"> <li>All except ReportUnsupported</li> </ul>	Incorrect test framework configuration. Feature unsupported.	None
<b>OATJams_Smoke (3)</b>	<ul style="list-style-type: none"> <li>All except ReportUnsupported</li> </ul>	Incorrect test framework configuration. Feature unsupported.	None

## 2.2.6 Media

### 2.2.6.1 Failures

Feature	Tests	Issue	Impact	Severity
<b>MediaDevice</b>	<ul style="list-style-type: none"> <li>MediaDevice_StereoAudioFiles</li> </ul>	Incorrect test framework configuration. DPK issue. Feature verified manually.	None	Low

Issue Severity	High	Medium	Low	Unknown	Total
<b>Totals</b>	0	0	1	0	1

### 2.2.6.2 Unexecuted

Test Module	Tests	Reason	Impact
<b>MediaDevice (1)</b>	<ul style="list-style-type: none"> <li>MediaDevice_StereoAudioFiles</li> </ul>	Incorrect test framework configuration. Test issue. Feature unsupported.	None
<b>OMADRM (23)</b>	<ul style="list-style-type: none"> <li>VerifyDisplayCount</li> <li>VerifyDisplayRightsEndTime</li> <li>VerifyDisplayRightsExpiredEndTime</li> <li>VerifyDisplayRightsExpiredInterval</li> <li>VerifyDisplayRightsStartTime</li> <li>VerifyDisplayRightsInterval</li> <li>VerifyExpiredDisplayCount</li> <li>VerifyExpiredPlayCount</li> <li>VerifyLicenseValidity</li> <li>VerifyPlayCount</li> <li>VerifyPlayCountZero</li> <li>VerifyPlayRightsEndTime</li> <li>VerifyPlayRightsExpiredEndTime</li> <li>VerifyPlayRightsExpiredInterval</li> <li>VerifyPlayRightsExpiredStartTime</li> <li>VerifyPlayRightsInterval</li> <li>VerifyPlayRightsStartTime</li> <li>VerifyPlayRightsConstraintCount</li> <li>VerifyRetrieveRightsConstraintInterval</li> <li>VerifyRetrieveRightsConstraintTime</li> <li>VerifyRightsChangeNotificati</li> </ul>	Incorrect test framework configuration. Test issue. Feature unverified.	Potential infringement of rights.

	<ul style="list-style-type: none"> <li>onExpired</li> <li>VerifyRightsChangeNotificati</li> <li>onSoonToExpire</li> </ul>		
<b>Image Decoders</b>	<ul style="list-style-type: none"> <li>UTGIFDecoder_Level1_Tests</li> <li>UTGIFDecoder_Level2_Tests</li> <li>UTGIFDecoder_Level3_Tests</li> <li>UTGIFDecoder_Level4_Tests</li> </ul>	Incorrect test framework configuration. Test issue. Feature verified.	None

## 2.2.7 Networking

### 2.2.7.1 Failures

Feature	Tests	Issue	Impact	Severity
<b>Socket Routines</b>	<ul style="list-style-type: none"> <li>Socket_Accept.3</li> <li>Socket_Close.3</li> </ul>	Incorrect test framework configuration. Test issue. Feature unverified.	Network server applications may have failures managing TCP connections	Medium
<b>Socket Port Number Routines</b>	<ul style="list-style-type: none"> <li>SockPort_Ipv4_Accept.3</li> <li>SockPort-Ipv4_Close.3</li> </ul>	Incorrect test framework configuration. Test issue. Feature unverified.	Network server applications may have failures managing TCP connections	Medium

Issue Severity	High	Medium	Low	Unknown	Total
<b>Totals</b>	0	2	0	0	2

### 2.2.7.2 Unexecuted

Test Module	Tests	Reason	Impact
None			

## 2.2.8 Performance

### 2.2.8.1 Failures

Feature	Tests	Issue	Impact	Severity
None				

Issue Severity	High	Medium	Low	Unknown	Total
<b>Totals</b>	0	0	0	0	0

### 2.2.8.2 Unexecuted

Test Module	Tests	Reason	Impact
PerfWatchTest (1)	PerfWatchTest_All	IncorrectTestFramework configuration. Test issue. Feature unverified.	Low

## 2.2.9 Security

### 2.2.9.1 Failures

Feature	Tests	Issue	Impact	Severity
CTFTestRootExistence	<ul style="list-style-type: none"> <li>CTFTestRootExistence_TestRootExistenceTest</li> </ul>	Expected to fail with internal CRM device build. Must pass on commercial device build.	None	Low

Issue Severity	High	Medium	Low	Unknown	Total
Totals	0	0	1	0	1

### 2.2.9.2 Unexecuted

Test Module	Tests	Reason	Impact
None			

## 2.2.10 System

### 2.2.10.1 Failures

Feature	Tests	Issue	Impact	Severity
Background	<ul style="list-style-type: none"> <li>BGAudioFGVoice</li> <li>ENDKeyBGVoice</li> <li>ENDKeyFGVoice</li> <li>InterruptWithVoice</li> <li>LaunchDuringVoice</li> <li>LaunchFGWithBGData</li> <li>LaunchSMSVoice</li> <li>LaunchWAPVoice</li> <li>PowerDown</li> <li>PowerUp</li> <li>TransitionToBG</li> </ul>	Incorrect test framework configuration. Tests obsolete.	Apps may not transition properly between foreground and background.	High
File System	<ul style="list-style-type: none"> <li>FileSystem2Test_Rename4</li> </ul>	Incorrect test framework configuration. Test issue. Feature unverified.	None	Low
OutOfCoverage	<ul style="list-style-type: none"> <li>OutOfCoverage_Runtime.4</li> </ul>	Incorrect test framework configuration. Test issue. Feature unverified.	None	Low
OutOfCoverage	<ul style="list-style-type: none"> <li>OutOfCoverage_OOC.3-5</li> </ul>	Platform issue. Failures are related to WiFi failure.	Applications cannot transfer data using WiFi.	High

Issue Severity	High	Medium	Low	Unknown	Total
Totals	2	0	2	0	4

### 2.2.10.2 Unexecuted

Test Module	Tests	Reason	Impact
Locales (1)	<ul style="list-style-type: none"> <li>Locales_CLocaleSL</li> </ul>	Incorrect test framework configuration. Test issue. Feature unverified.	Applications may not be able to use the llocale interface reliably.

## 2.2.11 TAPI

### 2.2.11.1 Failures

Feature	Tests	Issue	Impact	Severity
UMTS	UMTS_MPDP2.3	Incorrect device configuration.	Network applications that require multiple PDP contexts may not be able to operate.	Medium

Issue Severity	High	Medium	Low	Unknown	Total
Totals	0	1	0	0	1

### 2.2.11.2 Unexecuted

Test Module	Tests	Reason	Impact
None			

## 2.2.12 Telephony

### 2.2.12.1 Failures

Feature	Tests	Issue	Impact	Severity
MMS	<ul style="list-style-type: none"> <li>mmsEngine_&lt;All&gt;</li> </ul>	Incorrect test framework configuration. Test issue. Feature unverified.	MMS messaging may not work properly.	Medium
Smart Card	<ul style="list-style-type: none"> <li>ctfsmartcardiapplication_GetCPHSInfoTest</li> <li>ctfsmartcardiapplication_GetPKCS15TableNonProvAppTest</li> <li>ctfsmartcardiapplication_GetPKCS15TableRspNonProvAppTest</li> </ul>	Incorrect test framework configuration. Feature unsupported on test device.	The smartcard_IApplication_GetCPHSInfo and smartcard_IApplication_GetPKCS15TableRsp interfaces may fail.	Medium
Telephone	<ul style="list-style-type: none"> <li>Telephone_SetSubscriptionStatus</li> </ul>	Platform issue. Failure is related to WiFi issue.	Subscription status cannot be changed.	Medium

Telephone	<ul style="list-style-type: none"> <li>Telephone_SetWLANPreference</li> </ul>	Failure is related to WiFi issue.	WLAN preferences cannot be set.	Medium
-----------	---	-----------------------------------	---------------------------------	--------

Issue Severity	High	Medium	Low	Unknown	Total
Totals	0	4	0	0	4

## 2.2.12.2 Unexecuted

Test Module	Tests	Reason	Impact
ctfmmsEngine	<ul style="list-style-type: none"> <li>ctfEngine_Test*</li> </ul>	Incorrect test framework configuration. Tests obsolete.	None
ctfmmsmessage (5)	<ul style="list-style-type: none"> <li>ctfmmsmessage</li> </ul>	Incorrect test framework configuration. Test issue. Tests obsolete.	None
ctfsmartcardiapplicati on (1)	<ul style="list-style-type: none"> <li>ctfsmartcardiapplication_CreateDelay</li> </ul>	Incorrect test framework configuration. Test issue. Feature unsupported on target.	None
ctfsmartcardicard (2)	<ul style="list-style-type: none"> <li>ctfsmartcardicard_ICardPowerDown</li> <li>Ctfsmartcardicard_ICardPowerUp</li> </ul>	Incorrect test framework configuration. Test issue. Feature unsupported on target.	None
ctfsmartcardiperso (32)	<ul style="list-style-type: none"> <li>All</li> </ul>	Not executed pending availability of UICC cards that support the Perso feature.	Applications may not be able to use the smartcard_IPerso interface.
ctfsmartcardipin (25)	<ul style="list-style-type: none"> <li>All</li> </ul>	Not executed pending availability of UICC cards that support the Perso feature.	Applications may not be able to use the smartcard_IPin interface.
ctfsmartcardirefresh (8)	<ul style="list-style-type: none"> <li>All</li> </ul>	Not executed pending availability of UICC cards that support the Perso feature.	Applications may not be able to use the smartcard_Refresh interface.
ctfsmartcardislots (1)	<ul style="list-style-type: none"> <li>ctfsmartcardislots_CreateDelay</li> </ul>	Incorrect test framework configuration. Test issue. Feature unsupported.	None
SMS (1)	<ul style="list-style-type: none"> <li>STRUPDATESTATUS_REP ORT_Default</li> </ul>	Incorrect test framework configuration. Test obsolete.	None
Telephone (11)	<ul style="list-style-type: none"> <li>All interactive tests</li> </ul>	Incorrect test framework configuration. Test issue. Feature verified.	None
Uifsmilplayer (58)	<ul style="list-style-type: none"> <li>All</li> </ul>	Incorrect test framework configuration. Test issue. Feature unverified.	SMIL Player Widgets may not render properly

## 2.2.13 UI

### 2.2.13.1 Failures

Feature	Tests	Issue	Impact	Severity
UTCJKFonts	CJKFont_*	Incorrect test framework configuration. Feature unsupported on reference platform.	Expected to work on commercial device with fonts present.	Low

Issue Severity	High	Medium	Low	Unknown	Total
----------------	------	--------	-----	---------	-------

<b>Totals</b>	0	0	1	0	1
---------------	---	---	---	---	---

### 2.2.13.2 Unexecuted

Test Module	Tests	Reason	Impact
<b>FrameWidget (2)</b>	<ul style="list-style-type: none"> <li>CameraFrameModel</li> <li>MediaFrameModel</li> </ul>	Incorrect test framework configuration. Test issue. Tests obsolete.	None
<b>UTFontFactory (5)</b>	<ul style="list-style-type: none"> <li>UTFontFactory_FontData_Level1</li> <li>UTFontFactory_FontData_Level3</li> <li>UTFontFactory_Fontfactory_level1</li> <li>UTFontFactory_FontInfo_Level1</li> <li>UTFontFactory_FontInfo_Level2</li> <li>UTFontFactory_FontInfo_Level3</li> </ul>	Incorrect test framework configuration. Test issue. Non-existent tests.	None